Inspection Report Audits

Between 08/04/2010 and 09/29/2011

Consent = 24

New Licensee = 24

Total = 48

Audits performed by
Wilson Fausel – Audit Contractor

Index

Slide	Content
1	Cover
2	Index
3	Items Missed From Consent Audits
4	Items Missed From New Licensee Audits
5	Combined Consent and New Licensee Number Missed
6	Combined Consent and New Licensee Percentage Missed
7	Top 5 Items That Have The Biggest Impact on the Public

Top 9 Consent Items Missed

24 Reports Audited

	SOP Item	Description	#	%
•	.1111(a)-7	Presence or absence of an installed heating source	13	54%
•	.1112(a)(2)(B)	Presence or absence of an installed cooling source	13	54%
•	.1109(c)	Plumbing fixtures operated?	7	29%
•	.1106(b)-5	Describe ceiling structure	5	21%
•	.1105	Are excluded items documented properly?	4	17%
•	.1103(b)(3)(D)	Whether condition requires repair or more observation	3	13%
•	.1103(b)(3)(D)	The statements shall describe the component (DDID)	2	8%
•	.1108(b)-2	Report methods used to inspect roofing	2	8%
•	.1110(b)-4	Location of main and distribution panels	2	8%

Top 15 New Licensee Items Missed

24 Reports Audited

	SOP Item	Description	#	%
•	.1103(b)(3)(D)	The statements shall describe the component (DDID)	10	42%
•	.1112(a)(2)(B)	Presence or absence of an installed cooling source	10	42%
•	.1111(a)(7)	Presence or absence of an installed heating source	9	38%
•	.143-151.58(a1)	Statement included? "This summary is not the entire report	8	33%
•	.1103(b)(3)	Is report written and signed by the inspector	7	29%
•	.1103(b)(3)(D)	Whether condition requires repair or more observation	7	29%
•	.1110(b)(2)	Service entry conductor materials - describe	5	21%
•	.1106(b)(4)	Columns / piers - describe	4	17%
•	.1106(b)(5)	Ceiling structure - describe	4	17%
•	.1103(b)(3)	License number stated?	3	13%
•	.1105	Are excluded items documented properly?	3	13%
•	.1106(c)(3)	Report methods in crawl spaces and attics	3	13%
•	.1109(c)	Plumbing fixtures operated?	3	13%
•	.1110(b)(3)	Service type as overhead or underground	3	13%
•	.1111(b)(2)	Heating equipment and distribution type	3	13%

Top 15 Combined Items Missed

48 Reports Audited Number Missed

	SOP Item	SOP Description	New	Consent	Total
•	.1112(a)(2)(B)	Presence or absence of an installed cooling source	10	13	23
•	.1111(a)(7)	Presence or absence of an installed heating source	9	13	22
•	.1103(b)(3)(D)	The statements shall describe the component (DDID)	10	2	12
•	.1103(b)(3)(D)	Whether condition requires repair or observation	7	3	10
•	.1109(c)	Plumbing fixtures operated?	3	7	10
•	.1106(b)(5)	Ceiling structure - described	4	5	9
•	.143-151.58(a1)	Statement? "This summary is not the entire report	8	0	8
•	.1103(b)(3)	Is report written and <u>signed</u> by the inspector	7	0	7
•	.1105	Are excluded items documented properly?	3	4	7
•	.1110(b)(2)	Service entry conductor materials - describe	5	1	6
•	.1106(b)(4)	Columns / piers – describe	4	1	5
•	.1106(c)(3)	Report methods to inspect crawl spaces and attics	3	2	5
•	.1108(b)(2)	Report method used to inspect roof	2	2	4
•	1110(b)(4)	Location of main and distribution panel	2	2	4
•	.1110(b)(3)	Service type as overhead or underground	3	0	3
•	.111(b)(2)	Heating equipment and distribution - describe	3	0	3
•	.1103(b)(3)	License number stated?	3	0	3

Top 15 Combined Items Missed

48 Reports Audited Percentage Missed

	SOP Item	SOP Description	New	Consent	Total
•	.1112(a)(2)(B)	Presence or absence of an installed cooling source	42%	54%	48%
•	.1111(a)(7)	Presence or absence of an installed heating source	38%	54%	46%
•	.1103(b)(3)(D)	The statements shall describe the component (DDID)	42%	8%	25%
•	.1103(b)(3)(D)	Whether condition requires repair or observation	29%	13%	21%
•	.1109(c)	Plumbing fixtures operated?	13%	29%	21%
•	.1106(b)(5)	Ceiling structure - described	17%	21%	19%
•	.143-151.58(a1)	Statement? "This summary is not the entire report	38%	0	17%
•	.1103(b)(3)	Is report written and signed by the inspector	29%	0	15%
•	.1105	Are excluded items documented properly?	13%	17%	15%
•	.1110(b)(2)	Service entry conductor materials - describe	21%	4%	13%
•	.1106(b)(4)	Columns / piers – describe	14%	4%	10%
•	.1106(c)(3)	Report methods to inspect crawl spaces and attics	13%	8%	10%
•	.1108(b)(2)	Report method used to inspect roof	8%	8%	8%
•	1110(b)(4)	Location of main and distribution panel	8%	8%	8%
•	.1110(b)(3)	Service type as overhead or underground	13%	0	6%
•	.111(b)(2)	Heating equipment and distribution - describe	13%	0	6%
•	.1103(b)(3)	License number stated?	13%	0	6%

Top 5 Items That Have Biggest Impact on the General Public

•	SOP Item .1103(b)(3)(D) .1103(b)(3)(D) .143-151.58(a1) .1103(b)(3) .1103(b)(3)	SOP Description The statements shall describe the component (DDID) Whether condition requires repair or observation Statement? "This summary is not the entire report Is report written and signed by the inspector License number stated?	New 42% 29% 38% 29% 13%	Consent 8% 13% 0 0	Total 25% 21% 17% 15% 6%
•	.1109(c) .1106(b)(5) .1105 .1110(b)(2) .1106(b)(4) .1106(c)(3)	Plumbing fixtures operated? Ceiling structure - described Are excluded items documented properly? Service entry conductor materials - describe Columns / piers – describe Report methods to inspect crawl spaces and attics	13% 17% 13% 21% 14% 13%	29% 21% 17% 4% 4% 8%	21% 19% 15% 13% 10%
•	.1108(b)(2) 1110(b)(4) .1110(b)(3) .111(b)(2) .1112(a)(2)(B) .1111(a)(7)	Report method used to inspect roof Location of main and distribution panel Service type as overhead or underground Heating equipment and distribution - describe Presence or absence of an installed cooling source Presence or absence of an installed heating source	8% 8% 13% 13% 42% 38%	8% 8% 0 0 54% 54%	8% 8% 6% 6% 48% 46%