

**NC Department of Insurance
Office of the State Fire Marshal - Engineering Division
1202 Mail Service Center, Raleigh, NC 27699-1202
919-661-5880**

Mobile Home Feeders and Equipment Grounding Conductors

Code: 2005 Electrical Code

Date: March 1, 2005

Section: 550.33

Question:

A double wide mobile home is fed from a 200 ampere service panelboard on the side. A feeder is installed from the service panel, down the side, and under the home 30 feet, and up into the sub-fed panel. The feeder is size 4/0 aluminum service cable, 4-wire, which has a bare equipment grounding conductor, but is contained within a moisture resistance sheath with the other conductors. Is this equipment grounding conductor in a cable the same as an insulated equipment grounding conductor?

Answer:

No, Section 550.33 requires that for any feeder supplying a mobile home, four insulated, color coded conductors are to be installed. There is no exception, nor is a bare conductor of a cable considered to be insulated. Therefore, each conductor must have its own insulating covering.

Keywords:

mobile homes, manufactured homes, and mobile home parks